Billing Code: 4910-60-P

## DEPARTMENT OF TRANSPORTATION

Pipeline and Hazardous Materials Safety Administration

[Docket No. PHMSA-2013-0019] [Notice No. 13-03]

**Safety Advisory:** Unauthorized Marking of Compressed Gas Cylinders

**AGENCY:** Pipeline and Hazardous Materials Safety Administration (PHMSA), DOT.

**ACTION:** Safety Advisory Notice.

SUMMARY: This notice advises the public that PHMSA has confirmed the marking, service and/or sale of certain high pressure DOT specification cylinders marked with a requalification identification number (RIN) without performing a valid hydrostatic requalification test. Kraus Fire Equipment Co. marked DOT cylinders as tested without approval from the Associate Administrator to requalify DOT cylinders and without calibrating its required systems. This advisory addresses cylinders serviced or purchased from Flint Welding Supply Co, Flint, MI from approximately June 2010 to December 2012 and marked with an "A978" or a partial "A978" or just the Month/Year, without a RIN mark in the middle.

**FOR FURTHER INFORMATION CONTACT:** Kraus Fire Equipment Co., G-4080 S. Dort Highway, Burton, MI Telephone 810-744-4780, Mr. Richard Battstone, Jr., Owner.

**SUPPLEMENTARY INFORMATION:** Approximately 496 DOT 3AA and 3AL cylinders used in carbon dioxide service were improperly marked from approximately June 2010 to December 2012. Cylinders subject to this notice were serviced or purchased from Flint Welding Supply Co, Flint, MI and were marked with an "A978" or

a partial "A978" or just the Month/Year, without a RIN mark in the middle. Kraus Fire

Equipment Co. requalified cylinders provided by Flint Welding Supply Co. without

performing the series of safety tests and inspections required by the Hazardous Materials

Regulations. These improperly marked cylinders were not properly tested and may not

possess the structural integrity to safely contain their contents under pressure during

normal transportation and use. Extensive property damage, serious personal injury, or

death could result from a rupture of a cylinder. These cylinders should be considered

unsafe and unauthorized for the filling of hazardous material unless and until they are

first tested properly by an individual or company authorized by DOT to requalify DOT

specification cylinders. Cylinders described in this safety advisory that are filled with an

atmospheric gas should be vented or otherwise safely discharged by authorized

personnel. Individuals who identify a cylinder subject to this notice are advised to

remove it from service and return it to Flint Welding Supply Co, Flint MI.

Issued in Washington, D.C. on March 7, 2013.

R. Ryan Posten

Deputy Associate Administrator for Hazardous Materials Safety

[FR Doc. 2013-05678 Filed 03/12/2013 at 8:45 am; Publication Date: 03/13/2013]

2